


Appendix C - Construction Photos

An Example of a Valve Replacement - Check Valve 74



Stopple Valve - CKV - 74



Cutting the Pipe





CKV-74 and Section of Pipe Removed



Crane Lifts Valve Away from Site

***Corrosion Investigation/Repair
- Project #X019***



Buried Mainline Pipe is Excavated



**Special Burial Pipe , Refrigeration pipe,
Fiber Glass Reinforced Plastic heating
that has cracked,**



Sigma Coated Pipe.



**Structural Full Encirclement
Sleeve installed**



Insulation



Restoration of site

Buried Check Valve Investigations

